



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 10-26-10 Operator Robert L Bayless API #30-0 89-20110

Property Name Rock House Company Well No. 1 Location: Unit E Section 11 Township 24N Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing 55 Intermediate      Casing 60 Bradenhead 0 psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0		60		
10 min	0		60		
15 min	0		60		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	0
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE     

REMARKS:



By Adrian Lozano

Witness     

runner  
(Position)

E-mail address

ageiss@rlbayless.com