



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/19/10 Operator Black Hills Gas Res. API #30-0 39-26182
Property Name Juarilla 458 SS Well No. 2 Location: Unit 0 Section 7 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 20 Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>		<u>20</u>		
10 min	<u>Ø</u>		<u>20</u>		
15 min	<u>Ø</u>		<u>20</u>		
20 min	<u>Ø</u>		<u>20</u>		
25 min	<u>Ø</u>		<u>20</u>		
30 min	<u>Ø</u>		<u>20</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE N/A

REMARKS:

no water or pressure on bradenhead

By Kirt D. Vicenti
Lease operator
(Position)

Witness _____

E-mail address Kirt.Vicenti@bhep.com

