



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 10/27/10 Operator Blackhills Gas Res. API #30-0 39-26241
Property Name Jicarilla 459 50 Well No. 1 Location: Unit I Section 18 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing _____ Intermediate N/A Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>35</u>		
10 min	<u>0</u>		<u>35</u>		
15 min	<u>0</u>		<u>35</u>		
20 min	<u>0</u>		<u>35</u>		
25 min	<u>0</u>		<u>35</u>		
30 min	<u>0</u>		<u>35</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow _____	
Surges _____	
Down to Nothing _____	
Nothing <u>✓</u>	
Gas _____	
Gas & Water _____	
Water _____	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

no water or pressure on braden head

By Kurt Vicenti
lease operator
(Position)

Witness _____

E-mail address Kurt.Vicenti@bhep.com