



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-5-2010 Operator Black Hill Gas Resources API #30-0 26347

Property Name Jicavilla 451-3 Well No. 1 Location: Unit 13 Section 3 Township 29N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 34 Intermediate Casing 34 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				FLOW CHARACTERISTICS	
	Bradenhead		INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>34</u>			
10 min	<u>0</u>		<u>34</u>			
15 min	<u>0</u>		<u>34</u>			
20 min	<u>0</u>		<u>34</u>			
25 min	<u>0</u>		<u>34</u>			
30 min	<u>0</u>		<u>34</u>			

Steady Flow

Surges

Down to Nothing

Nothing ✓

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Replace 1" Valve on Braden Head.

By Chris Heclaup
Lease operator
(Position)

Witness

E-mail address

