

5053279207

Benson-Monlin-Greer

03:37:34 p.m. 07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
ARTIFICIAL LIFT DISTRICT OFFICE
1000 RIO BRAZOS ROAD
ALBUQUERQUE, NM 87102
(505) 334-6170 FAX: (505) 334-6170
<http://omnr.dnr.state.nm.us/ocad/District/IV3a/extra.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/11/10 Operator Benson Monlin Greer API #30-0 37-29249Property Name Pice Fed Well No. 1 Location: Unit E Section 34 Township 25N Range 24WWell Status (Shut-In or Producing) Initial PSI: Tubing 96 Intermediate 111 Casing 96 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	Bradenhead					
	BH	Int	Csg	Int	Csg	
TIME						
5 min						
10 min						
15 min						
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing X _____
Gas _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By Ben F. Greer

Witness _____

(Position)

E-mail address _____

