

## NEW MEXICO UNDEGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 10-7-10 Operator Black h///s GR API #30-0 30080	
Property Name 29-2-9 Well No. 143 Location: Unit Section 9 Township 29N Range 2W	
Well Status(Shut-In or Producing) Initial PSI: Tubing Intermediate Casing 50 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
BH Int Csg Int Csg	
5 min 0 50	Steady Flow
10 min 0 50	Surges
15 min 0 50	Down to Nothing
20 min 0 50	Nothing
25 min 0 50	Gas
30 min 0 50	Gas & Water
	Water
If hyadanhaad flawed water sheek all of the descriptions that apply below.	
CLEAR FRESH SALTY SULFUR BLACK  5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE  REMARKS:    CLEAR FRESH SALTY SULFUR BLACK   CONS. DIV. DIST. 3   CONS. DIST. DIST. DIST. DIV. DIST. 3   CONS. DIV. DIST. 3   CONS. DIST. DIST. DIST. DIST. D	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE STECEIVED	
S MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE (S) NOV 2010	
REMARKS:	
CZZ NOLGLIN	
05.61.81.17	
By Judson Valder  lease Operator (Position)  E-mail address Judice BAEPLOIP.com	Vitness
lease operator	
(Position)	
E-mail address VIVICORNEPCOSP.COM	