

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emprd.state.nm.us/ocd/District III/3district.htm](http://emprd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9-2-10 Operator Dugan Production Corp API # 30-043-20318
Property Name Dome Rusty 30-22-6 Well No. 1 Location: Unit B Section 30 Township 22N Range 06W
Well Status(Shut-In or Producing) Initial PSI: Tubing 160 Intermediate N/A Casing 220 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0	N/A	220			
10 minutes	0	N/A	220			
15 minutes	0	N/A	220			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:



By

Curtis Davis

Witness

Switcher
(Position)