

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9-2-10 Operator Dugan Production Corp API # 30-043-20320
Property Name Dome Rusty 24-22-7 Well No. 1 Location: Unit J Section 24 Township 22N Range 07W
Well Status(Shut-In or Producing) Initial PSI: Tubing Ø Intermediate N/A Casing 45 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm			FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg		BRADENHEAD	INTERMEDIATE
5 minutes	Ø	N/A	45			Steady Flow		
10 minutes	Ø	N/A	45			Surges		
15 minutes	Ø	N/A	45			Down to Nothing		
20 minutes						Nothing		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

Ø

INTERMEDIATE

N/A

REMARKS:



By

Curtis Davis

Witness

Switcher

(Position)