



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-2010 Operator Energen Resources API # 3003906733

Property Name JICARILLA WEST 6 Location: Unit D Section 6 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 120 Intermediate Casing 125 Bradenhead 65

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>18</u>	<u>125</u>				Steady Flow	☒	
10 minutes	<u>22</u>	<u>125</u>				Surges		
15 minutes	<u>23</u>	<u>125</u>				Down to Nothing		
20 minutes	<u>24</u>	<u>125</u>				No Flow		
25 minutes	<u>24</u>	<u>125</u>				Gas		
30 minutes	<u>26</u>	<u>125</u>				Gas and Water		
5 minute SI	<u>10</u>	<u>125</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur

5 Minute Shut-in Bradenhead 10 psi Intermediate

REMARKS:

Bradenhead pressure has a steady flow.

By Alex Harvey
Field Operator
(Position)

Witness

