



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-MAR-2011 Operator MCCELLIGAN API #30-0 45-35043
Property Name BIGULP Well No. 1 Location: Unit 2 Section 20 Township 30 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 445 Intermediate N/A Casing 2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		2		
10 min	0		2		
15 min	0		2		
20 min	0		2		
25 min	0		2		
30 min	0		2		

FLOW CHARACTERISTICS

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing ☒ _____
Gas _____
Gas & Water _____
Water _____



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:
OPENED B/H TO BLOW DOWN, NOTHING CAME OUT
PRESSURE ON CASING WAS 2135 FOR FULL 30 MINUTES

By [Signature] Witness [Signature]
(Position)

E-mail address _____