



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 4-13-11 Operator Burlington Res API #30-0 39-25912
Property Name San Juan 29-7 lot Well No. 353 Location: Unit Section 9 Township 29 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 103 Intermediate N/A Casing 135 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		134		
10 min	0		133		
15 min					
20 min					
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	
Nothing		
Gas	/	
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Head at 10 seconds.

Well kicked on while doing test.

By Shay Wint

Witness Monica Kuchling

MISO
(Position)

E-mail address