



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-13-11 Operator Burlington API #30-0 39-2984

Property Name Sun Juan 29-7 Well No. 34M Location: Unit _____ Section 4 Township 29 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 111 Intermediate 92 casing 162 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	0		162	0	162	Steady Flow	
10 min	0		162	0	162	Surges	
15 min	0		162	0	162	Down to Nothing	/
20 min						Nothing	
25 min						Gas	/
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH dead at 8 seconds -
Int. to nothing in 20 seconds.
Well flowing during test

By Shy Wata
MISO
(Position)

Witness Monica Kuehling

E-mail address _____

