



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-MAY-2011 Operator COMCO/DeLuna API #30-0 45-2694
Property Name STULL Well No. 100 Location: Unit ___ Section 10 Township 32 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing 18 Intermediate ___ Casing 18 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS		
	BH	Bradenhead	INTERM	BRADENHEAD	INTERMEDIATE	
TIME		Int	Csg			
5 min			<u>18</u>	Steady Flow		
10 min			<u>18</u>	Surges		
15 min			<u>18</u>	Down to Nothing <u>✓</u>		
20 min			<u>18</u>	Nothing		
25 min			<u>18</u>	Gas		
30 min			<u>18</u>	Gas & Water		
				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE ___

REMARKS:

OPENED BRADENHEAD BLEW DOWN TO
NOTHING IN LESS THAN 1 SECOND

By Chris Hoff

Witness John

(Position)

E-mail address _____

