



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-MAY-2011 Operator CONOCO/BIRMINGHAM API #30-0 45-27680
Property Name BONDS LUM Well No. 100 Location: Unit Section 15 Township 32 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing 3 Intermediate Casing 7 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			7		
10 min			7		
15 min			7		
20 min			7		
25 min			7		
30 min			7		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD .6

INTERMEDIATE

REMARKS:

OPENED BRADEN HEAD BLEW DOWN TO NOTHING
IN LESS THAN 1 SECOND 5 MINUTE SHUT IN .6

By Chris Todd

Witness John Williams

(Position)

E-mail address



