

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Enterprise Field Services LLC	Contact: Don Fernald
Address: c/o Environmental Dept. P.O. Box 4324 Houston, Texas 77210-4324	Telephone No. 505-599-2124
Facility Name: Manzanares / Trunk R Pipeline	Facility Type: pipeline - gathering

Surface Owner: Enterprise	Mineral Owner	Lease No.
---------------------------	---------------	-----------

LOCATION OF RELEASE

Unit NE/4	Section 17	Township 29 N	Range 9 W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
--------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	--------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 1463 mcf	Volume Recovered: 0
Source of Release: Pipeline	Date and Hour of Occurrence before 5/17/10 - 4:30 PM	Date and Hour of Discovery 5/17/10 - 4:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell / NMOCD - Aztec, NM	
By Whom? Don Fernald	Date and Hour: 5/18/10 - 2:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**NMOCD MAY 21 11:10
OIL CONSERV. DIV.
DIST. 3**



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A small "pin hole" was found in a gathering pipeline (Trunk R). To accommodate repairs, 1463 mcf of gas was blown down.

Describe Area Affected and Cleanup Action Taken.*
Pipeline repaired and placed back in service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor:	
Printed Name: Don Fernald	 For: CP	
Title: Environmental Scientist	Approval Date: 9/22/10	Expiration Date:
E-mail Address: dfernaldd@eprod.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/18/10 Phone: 505-599-2124		

* Attach Additional Sheets If Necessary

nBP1026628063