

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30 045 26970

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 320-2653
Facility Name	Pump Canyon SWD	Facility Type	SWD Well

Surface Owner	Fed	Mineral Owner	Fed	Lease No.	SF-078596
---------------	-----	---------------	-----	-----------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	7	30N	8W	1725	SOUTH	1850	EAST	San Juan

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	5 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Storage tanks #9 and #10	Date and Hour of Occurrence	5/17/2004 9:00:00 AM	Date and Hour of Discovery	5/17/2004 9:00:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Gregg Wurtz	Date and Hour	5/18/2004 9:15:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	44.0		

If a Watercourse was Impacted, Describe Fully.\*

None impacted



Describe Cause of Problem and Remedial Action Taken.\*

Leak in bottom of tank is suspected based on visible surface water observed close to pump building. Currently inspecting tanks on location to identify source of water release. Tanks will be cleaned, inspected, and coated prior to being put back into service. Soils were removed at surface and transported off location to landfarm facility

Describe Area Affected and Cleanup Action Taken.\*

Area directly under tanks and down gradient 20 feet near filter building at 1-2 feet below grade surface

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
			
Printed Name:	Approved by District Supervisor:		
Gregg Wurtz	for Frank Chavez		
Title: Environmental Representative	Approval Date:	5/24/04	Expiration Date:
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc. com	Conditions of Approval:		Attached
Date: 5-20-04 Phone: (505) 326-9841 or 9537			<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NDGF0414537246