<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr∞ Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action	
30 045 32472	OPERATOR Initial Report Final Report
Name of Company BP America	Contact Donald Brooks
Address 200 Energy Court	Telephone No. (505) 326-9425
Facility Name Kernaghan B 8S	Facility Type Gas Well
Surface Owner: Federal Mineral Owner	Lease No. NMSF -078387-A
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the North	/South Line Feet from the East/West Line County San Juan
Latitude 36.51400 Longitude 107.41100	
NATURE OF RELEASE	
Type of Release: Coal fines	Volume of Release: NA Volume Recovered: NA
Source of Release; Rain water collected coal fines around location.	Date and Hour of Occurrence Date and Hour of Discovery
Was Immediate Notice Given?	Unknown 11/5/04 3:45 PM If YES, To Whom?
Was infinediate Notice Given: ☐ Yes ☐ No ☐ Not Required	Left phone message to Denny Foust
By Whom? Don Brooks	Date and Hour 11/5/04 4:30 PM
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*	
Describe Cause of Problem and Remedial Action Taken.*	
BP engineer was driving in the area of this well and noticed black particles in a dry wash area off of our well pad. She got out of the vehicle and followed	
the wash back to our well site. It was then given to our drilling group to help us understand what had happened. The well was drilled during rainy weather, and as they were flaring, coal fines were hitting the flare pit and blowing over the edge of the pit. The rainwater washed these coal fines down into a small	
dry wash, where we found them. It affected about 25 yards in the small wash.	
Describe Area Affected and Cleanup Action Taken.*	
A roustabout crew was dispatched to shovel up what coal fines they can, dump them into the reserve pit, and rake the remaining particles into the	
surrounding dirt. There were no production fluids involved with this notification, just coal fines carried by rain water.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other	
federal, state, or local laws and/or regulations.	
~ 0	OIL CONSERVATION DIVISION
Signature: Signature:	Henry Jant
Printed Name: Donald Brooks	Approved by District Supervisor: for Frank Chavez
Timed Name. Donard Brooks	10. Trunk Charles

Phone: 326-9425

Title: Field Environmental Coordinator

E-mail Address: brooksd2@bp.com

Date: 11/18/2004

Conditions of Approval:

Expiration Date:

Attached

^{*} Attach Additional Sheets If Necessary