District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue. Artesia, NM 88210
District III
1000 Rio Brazos Road. Aztec. NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action **OPERATOR** ✓ Initial Report Final Report Name of Company Burlington Resources Contact Gregg Wurtz Telephone No. (505) 320-2653 P.O. Box 4289 Farmington NM 87499 Facility Name SAN JUAN 28-6 UNIT 130M Facility Type Gas Well Mineral Owner Surface Owner Fed Lease No. NMSF-079051 LOCATION OF RELEASE Unit Letter Township Feet from the North/South Line Feet from the East/West Line Section Range County San Juan 32 028N 006W 1700 South 820 East NATURE OF RELEASE Type of Release Volume of Release 22 bbls oil and 3 bbls water 25 BBLS. Volume Recovered O BBLS. Source of Release Date and Hour of Discovery Production Storage tank Date and Hour of Occurence 10/25/2004 4:00:00 PM 10/25/2004 7:00:00 AM Was Immediate Notice Given? If YES, To Whom? Yes No V Not Required By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ✓ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Corrosion hole on the side of the Production Tank, 6 inches from bottom. Corrosion could not be seen from outside of tank until hole developed. Soil excavated under and around tank and landfarmed on location. Work in progress. Describe Area Affected and Cleanup Action Taken.* Area around base of tank. Contained within the berm. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Approved by District Supervisor: Printed Name: Title: Environmental Representative Approval Date: E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com Landtavan to be Phone: (505) 326-9841or 9537