

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America Production Company	Contact Brittany Benko
Address 200 Energy Court Farmington, NM 87401	Telephone No. (505) 326-9235
Facility Name Pritchard 5M	Facility Type Wellsite

Surface Owner BLM	Mineral Owner BLM	Lease No. 30-045-31812 NM-013585
--------------------------	--------------------------	--

LOCATION OF RELEASE

Unit Letter H	Section 34	Township 31N	Range 9W	Feet from the 2005	North/South Line FNL	Feet from the 905	East/West Line FEL	County San Juan County
-------------------------	----------------------	------------------------	--------------------	------------------------------	--------------------------------	-----------------------------	------------------------------	----------------------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 160 bbls	Volume Recovered 160 bbls
Source of Release Frac Tank	Date and Hour of Occurrence 11/23/2003 6:00AM	Date and Hour of Discovery 11/23/2003 6:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? Don Brooks	Date and Hour November 23, 2003 7:50 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The water haulers were filling frac tanks with produced water when the tire chains hanging from the rear of the truck hooked the hose that was attached to the load valve, and snapped the valve off of the tank.

Describe Area Affected and Cleanup Action Taken.*

The produced water was diverted to the reserve pit. The produced water will be evaporated from the pit during the completion operations of this well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brittany Benko</i>	OIL CONSERVATION DIVISION	
Printed Name: Brittany Benko	Approved by District Supervisor: <i>Denny G. Foust</i> <i>for Frank Chavez</i>	
Title: Environmental Coordinator	Approval Date: 12/11/03	Expiration Date:
Date: 12/04/2003 Phone: (505) 326-9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DGF0332835707