


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-045-32020

OPERATOR Initial Report ☒ Final Report ☐

Name of Company Devon	Contact Dwane Oliver
Address	Telephone No. 505-320-8135
Facility Name NEBU 435A	Facility Type Reserve Pit

Surface Owner BLM	Mineral Owner Devon	Lease No. SF-079010
-------------------	---------------------	---------------------

LOCATION OF RELEASE

Unit Letter D	Section 1	Township 30N	Range 8W	Feet from the 1100'	North/South Line North	Feet from the 1200'	East/West Line West	County San Juan
------------------	--------------	-----------------	-------------	------------------------	---------------------------	------------------------	------------------------	--------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Over spray from evaporating reserve pit	Volume of Release bbls 10	Volume Recovered 0
Source of Release Reserve pit	Date and Hour of Occurrence 4/28/04, 10:00 AM	Date and Hour of Discovery 4/29/04, 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust, Ray Sanchez, Darren Segrest, Darren Smith, Steve Zink	
By Whom? Dwane Oliver	Date and Hour 4/29/04 1:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Overspray from evaporating a reserve pit pooled up and broke through a small earthen dam, washing down the backside of location.

Describe Area Affected and Cleanup Action Taken.\* 50' X 40' sagebrush flat, when we reclaim reserve pit we will clean up then.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dwane Oliver</i>	OIL CONSERVATION DIVISION	
Printed Name: Dwane Oliver	Approved by District Supervisor: <i>Denny Foust for Frank Chavez</i>	
Title: Construction Supervisor	Approval Date: 5/06/04	Expiration Date:
E-mail Address: Dwane.Oliver@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/29/04	Phone: 505-320-8135	

\* Attach Additional Sheets If Necessary

n DGF0412157017