

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Williams Midstream	Contact	Aaron Dailey
Address	188 County Road 4900	Telephone No.	(505) 632-4708
Facility Name	Lateral A-7 pipeline	Facility Type	Pipeline
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	6	29 N	11 W					San Juan

GPS: N 36*75696 W 108*02879

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	: 405 MCF	Volume Recovered	: None
Source of Release:	Leaking 4" pipe on lateral A-7	Date and Hour of Occurrence	8/30/2010 @ 19:00 hours	Date and Hour of Discovery	8/30/2010 @ 19:00 hours
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Courtesy notice to Brandon Powell, Environmental Bureau, Aztec District Office		
By Whom?	Aaron Dailey—Courtesy notification was given	Date and Hour	9/1/2010 @ 09:00 hours		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RCVD SEP 10 '10

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV.

Describe Cause of Problem and Remedial Action Taken:



A citizen contacted Williams and local fire department noting a pipeline leak on lateral A-7. Upon notification, Williams representatives shut in all wells tying into the pipeline and coordinated for the repairs of the 4" pipe. No impact to soil, groundwater or vegetation was apparent during the repair/remediation activities.

Describe Area Affected and Cleanup Action Taken:

Natural gas loss was to atmosphere. No soil or groundwater was contaminated as a result of this release and subsequent repair.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor:  For: CP	
Printed Name: Aaron Dailey	Approval Date: 9/21/10	Expiration Date:
Title: Environmental Specialist	Conditions of Approval:	
E-mail Address: aaron.dailey@williams.com	Attached <input type="checkbox"/>	
Date: 9.8.2010	Phone: (505) 632-4708	

* Attach Additional Sheets If Necessary

nBP1026432531

5

Release Report Form



Release Report ID:
944

Williams Midstream or Williams Field Service Incident Notification

Contact a Release Reporting contractor at 1-800-688-6747 to report all on-shore releases (suspected or confirmed)
Call O'Brien Oil Pollution Services at 1-985-781-0804 to report all off-shore releases (suspected or confirmed)

1. Name and Title of Individual Reporting: Barker, Rusty (Operations/Technician Sr)

Call Back Phone Numbers: 505-632-4495 (Office)

505-320-7807 (Mobile)

Email: Russell.T.Barker@Williams.com

Address: 190 County Road 4980
Bloomfield, NM 87413

N36°, 75696
W 102°, 02879

Release Location - Pipeline Release

2. Emergency assistance required: No

3. Drill: No

3a. If Other:

4. Date and Time Release Discovered: 8/30/2010 7:00PM

Date and Time Report Created: 9/1/2010 11:14AM

5. Facility/ Pipeline where the release occurred: Lateral A-7

6. Facility or Pipeline: Pipeline

7. DOT Jurisdiction: No

8. State of Release: NEW MEXICO

9. Area: FCA

10. District: FCA-South Mesa View

11. Nearest City and State: Farmington, New Mexico

12. County / Parish: San Juan

13. Section: 6

14. Township: (or Latitude) 29 N

15. Range: (or Longitude) 11 W

16. Product Released:

Product	Gas/ Liquid	Qty Released	Qty Contained	Qty Recovered from Soil	Total Amt Recovered	Fully Contained	Stopped/ Contained	Date Stopped	Release Source
Natural Gas	Gas	405 MCF	0 MCF	0 MCF	0 MCF	No	Stopped	8/30/10 8:50 pm	pipe

Release Report Form



Release Report ID:
944

Williams Midstream or Williams Field Service Incident Notification

Contact a Release Reporting contractor at 1-800-688-6747 to report all on-shore releases (suspected or confirmed)
Call O'Brien Oil Pollution Services at 1-985-781-0804 to report all off-shore releases (suspected or confirmed)

Incident Summary

17. Release goes outside the Facility Boundary: No

18. Stream or Waterway effected: No

18a. Name of Stream or Waterway:

19. Incident Description / Summary:

The leak was found within 24 hours on the pipe

20. Mitigation Measures:

Immediately blocked in the lateral line

21. Soil Disposition:

N/A

Release Report Form



Release Report ID:
944

Williams Midstream or Williams Field Service Incident Notification

Contact a Release Reporting contractor at 1-800-688-6747 to report all on-shore releases (suspected or confirmed)
Call O'Brien Oil Pollution Services at 1-985-781-0804 to report all off-shore releases (suspected or confirmed)

Causes and Conditions

22. Preliminary Pre-Investigation Cause:

Corrosion-External: <input checked="" type="checkbox"/>	Incorrect Operation Contractor: <input type="checkbox"/>	Material or Weld Failure <input type="checkbox"/>
Corrosion-Internal: <input type="checkbox"/>	Incorrect Operation Operator: <input type="checkbox"/>	Natural Forces: <input type="checkbox"/>
Equipment Failure: <input type="checkbox"/>	Intentional Blow Down: <input type="checkbox"/>	Non-Maintenance: <input type="checkbox"/>
Excavation Damage: <input type="checkbox"/>	Maintenance: <input type="checkbox"/>	Third Party Damage: <input type="checkbox"/>
Other: <input type="checkbox"/>	Comment:	

23. Weather Conditions:

Calm: <input checked="" type="checkbox"/>	Raining: <input type="checkbox"/>	Sunny: <input checked="" type="checkbox"/>
Cloudy: <input type="checkbox"/>	Sleeting: <input type="checkbox"/>	Windy: <input type="checkbox"/>
Hailing: <input type="checkbox"/>	Snowing: <input type="checkbox"/>	

Incident Criteria

24. Hospitalization:	0
25. Media Coverage:	No
26. Fatality:	0
27. Injury:	0
28. Fire:	No
29. Explosion:	No
30. Preliminary Loss Damage Estimate:	Zero to < \$50k
31. Release reportable based on the Release/Spill Matrix:	No

Release Report Form



Release Report ID:
944

Williams Midstream or Williams Field Service Incident Notification

Contact a Release Reporting contractor at 1-800-688-6747 to report all on-shore releases (suspected or confirmed)
Call O'Brien Oil Pollution Services at 1-985-781-0804 to report all off-shore releases (suspected or confirmed)

Agencies Contacted:

Agency	Date	Name & Title	Contact Number	Comments:	City & State
--------	------	--------------	----------------	-----------	--------------

Contacts / Follow-up:

33. Operations Eric Edmanson
34. Safety: Nicole Reid
35. Environmental: Aaron Dailey PH:(505-632-4708)

Information in the fields below must be updated within 45 days

Mitigation/Remediation Follow-Up:

Qty of soil, water, or product removed:

Disposition of soil, water, or product removed: