

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	<b>Burlington Resources, a Wholly owned subsidiary of ConocoPhillips Company</b>	Contact	<b>Kelsi Gurvitz</b>
Address	<b>3401 E. 30<sup>th</sup> St., Farmington, NM 87402</b>	Telephone No.	<b>505-599-3403</b>
Facility Name	<b>San Juan 29-7 Unit #80A</b>	Facility Type	<b>Gas Well</b> <b>API # 300-39-23882</b>
Surface Owner	<b>Fee</b>	Mineral Owner	<b>Fee</b> <b>Lease No.</b>

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>C</b>	<b>09</b>	<b>T29N</b>	<b>R07W</b>	<b>1190'</b>	<b>North</b>	<b>1810'</b>	<b>West</b>	<b>Rio Arriba</b>

Latitude 36.74475° N Longitude 107.5789° W

### NATURE OF RELEASE

Type of Release – <b>Crude Oil</b>	Volume of Release – <b>5 BBL</b>	Volume Recovered – <b>0 BBL</b>
Source of Release: <b>Pit Tank</b>	Date and Hour of Occurrence <b>unknown</b>	Date and Hour of Discovery <b>2/15/10 1:00 p.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	<b>RCVD FEB 24 '10 OIL CONS. DIV.</b>
By Whom?	Date and Hour –	<b>DIST. 3</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\* **On February 15, 2010, it was discovered that as the B Valve was venting it was causing the pit tank to spray product around the surface & sides of the pit tank. Upon discovery, the well was shut in. No product was recovered.**

Describe Area Affected and Cleanup Action Taken.\* **All product remained within the bermed area. COPC will excavate the hydrocarbon impacted soil and complete confirmation sampling.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelsi Gurvitz</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: <b>Kelsi Gurvitz</b>	Approved by District Supervisor: <i>Bob Bell</i> For: CP	
Title: <b>Environmental Consultant</b>	Approval Date: <b>4/9/10</b>	Expiration Date:
E-mail Address: <b>kelsi.m.gurvitz@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>2/22/10</b> Phone: <b>505-599-3403</b>		

\* Attach Additional Sheets If Necessary

NRMB 1010956374