

Date Inspected: 4-10-96

Operator: Capital Oil & Gas Corp

Well No: 2

Location; U.L.S.T.R.: P 35-161-6W

Pool: Dakota

Were Pictures taken: yes

Description of Subject or Picture: 1 - of well head.

By: Frank Chavez & Ernest Cardona

Property Name: Thomas Drought

Footage: 330' FSL - 660' FEL

A.P.I. No: 30-081-05008

Number: 1

Inventory:

Description of Well head: well has csg head of 4 1/2" csg + pumping tee.

Surface:

Intermediate:

prod csg: 4 1/2" - 11# @ 806'

Tbg: 2 3/8"

rods: has rods in well, size unknown, polish rod looking up from pumping tee.

Production Equipment: None

Tanks: None

Pits: None

Remediation Required: y. n: