

○			

**(SUBMIT IN TRIPLICATE)**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_

Lease No. 2000

Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

7 Jan. 1948

Well No. 16-1 is located 600 ft. from N line and 100 ft. from E line of sec. 10

(1/4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)
(Field)	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 7 1 ft.


## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudline, job cementing points, and all other important proposed work)

oil - 100 gal by 100 lb. oil can, sent as follows:

Oil - 100 gal	100 sacks, with marker
Oil - 100 gal	100 sacks
Oil - 100 gal	100 sacks
Oil - 100 gal	100 sacks
Oil - 100 gal	100 sacks
Oil - 100 gal	100 sacks

0-2 inch or less in depth .75 surface ore left in mine (c-a 100 tons)  
backed up (circled).



**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company John Deere

Address 7111 34th

Attachment

By Henry S. Bridgman  
Title Connecting Geologist

