

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Allottee _____
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF AGREEMENT TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHUT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 7, 1962

Well No. Navajo 1 is located 2310 ft. from S line and 330 ft. from E line of sec. 14

SE 1/4 14
(Section and No.)

15N
(Twp.)

10W
(Range)

NMPM
(Meridian)

Walker Dome
(Field)

McKinley
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of all casings, depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Well was drilled to T. D. of 2347' in 1957 by Marion Oil Company. No report submitted to U. S. G. S. Halliburton Oil Well Cementing Co. Reports indicate the well was plugged with 150 sacks of cement from 2265' to surface.

In accordance with agreement between surface land owner and lessee, no dry hole marker was erected and the pits were left open. Gally and rat hole have been filled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Walker Dome Oil Company

Address Box 1323, Flagstaff, Ariz.

WALKER DOME OIL COMPANY

By Paul J. Zablitt

Title Secretary