## STATE OF NEW MEXICO



## ENERGY, MINERALS and NATURAL RESOURCES DIVISION OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE



BRUCE KING GOVERNOR

ANITA LOCKWOOD CABINET SECRETARY

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

August 9, 1994

MR TOM KNOWLTON NERDLIHC COMPANY INC 337 E SAN ANTONIO DRIVE SUITE 101 LONG BEACH CA 90807

RE: BULLSEYE #2 N-18-16N-09W BULLSEYE #9 O-18-16N-09W BULLSEYE #8 D-19-16N-09W BULLSEYE A #2 P-13-16N-10W

Dear Mr. Knowlton:

Your intents to place the above referenced wells on Temporarily Abandon status while a study is being conducted for a water injection project in the Marcelina Dakota Pool, are not feasible for the following reasons:

The **Bullseye** #8 was lost while drilling at 732' in 1978. The well is uncased and it is my understanding that 3 drill collars were left in the hole and that circulation was lost and could not be re-established. This well will not be considered as a candidate for an injection well and must be plugged and abandoned.

The **Bullseye** #9 was drilled to and completed in the Hospah or Gallup in 1979 has 5 1/2" casing set at 932' and is perforated from 836'-850'. The completion report indicated the well was a dry hole. The depth of the well and the well bore configuration would in my estimation preclude it from becoming a **CANDIDATE** for a Dakota injection well. This well must also be plugged and abandoned.

The status of the **Bullseye A #2** is cloudy. It was drilled to 897' in the Hospah or Massive Gallup in 1957 by Elmer L. White, and was known as the Walker Dome Santa Fe #1 or Santa Fe 16-10 #1. Paul Slayton filed an intent to re-enter the well, deepen it to 986' and swab test the Massive Gallup. We have no reports indicating this work was done. Lewis C. Jameson filed an affidavit of responsibility for conversion to a domestic water well for Paul Slayton in 1982.

Mr. Tom Knowlton Page 2

This was notarized and signed by the landowner R.M. Albers. The request was <u>not</u> approved by this office. We need more information on the present status of the well before a determination can be made as to its disposition.

To place the **Bullseye** #2 (or any well) on a temporarily abandoned status you must comply with Rule 203. This will require cutting off and fishing out the 14 joints of 2 3/8" tubing and setting tool left on top of a cast iron bridge plug at 932', drilling out the bridge plug and setting another bridge plug within 100' of the top perforation at 1730', loading the casing with an inert fluid and running a mechanical integrity test by pressuring the casing to 500 PSI for 30 minutes with a pressure loss of no more than 10%. If the test fails you will be required to repair the casing or plug and abandon the well within 90 days. If the well has mechanical integrity it may remain on a temporarily abandoned status for up to 5 years before plugging or returning it to beneficial use. All mechanical integrity tests will be witnessed by personnel from this office.

If you have any questions you may call me at 505-334-6178.

Yours Truly,

Charles Gholson

Deputy Oil & Gas Inspector

Chirles It holev

CG/cs

xc:

Rand Carroll - OCD Santa Fe

Well Files Operator File

Total 3 Capies to Appropriate District Offices	OIL CONSERVATION DIVISION		Post CUS Botted 14-0	
PATENCET PARTY STATE STATE STATE			WILLIAM NO.	Y-200
DESTRUCT II P.O. Danner D.D., Astrofo, 1984 88216	Sunta Po, New Mexico		S. Indexts Type of Laster	
DESTRUCT IN 1000 has Busines Rd., Amer. 1884 \$7410			STATE L	70E 🛂
1000 Ein Heisen Rd., Arme, 1944 SPAN			& Sair CE & Go Low He	
( DO NOT USE THIS FORM FOR P OFFERENT RES	ITICES AND REPORTS ON WEL ROPOSALS TO DRILL OR TO DEEPEN ERVOIR, USE "APPLICATION FOR PER (C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lam Name of Unit Agreement Name	
Type of Well:			BULLSEYE	
Name of Operator			E. Well No.	
NERDLING C	OMPANY, INC.		A2 - A Red was or Wilder Marcelina	
337 E San Antoni	o Dr. Suite 101	•	Marcelina	
- ·	0 Fee From The South	<u> 14 990</u>	For Prom The East	1ine
Series 13	Towards 16N In	] OW OF, RES., RT, GR, etc.)	McKinley	
		Yahan afiliation D		
	k Appropriate Box to Indicate I NTENTION TO:		SEQUENT REPORT OF:	
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REJEDIAL WORK	ALTERING CASIN	3 D
EMPORARELY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS. PLUG AND ABANE	CONMENT .
ULL OR ALTER CASING	_	CASING TEST AND CE	SOL THEME	
mer:		OTHER:	•	
teasibility is co be submitted upon completed by Sept	empleted. Subseque a completion. Esti ember 15, 1994.	mate integr	ity verification v	vill be
i i i i i i i i i i i i i i i i i i i		Øn.	AUG - 8 1994 L7	
		QUU	COM. DIV. Dist. 3	
1000 L	1 may 1 100	President	Augus	st_4, 1994
				HA-622-12
TOPOGRAPHICAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN	Control of the contro			
		1		P.02
		***		

NOT APPROVED