



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. WM 011452
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

26 October, 1962

Well No. 8-1 is located 330 ft. from N line and 330 ft. from E line of sec. 8
Sec. 8 (1/4 Sec. and Sec. No.) 16 W 12 N P.M.M.
 (Twp.) (Range) (Meridian)
ildcat McKinley New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7401 ft. est.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Following instructions of Mr. P. T. McGrath, the well was plugged with 15 sacks of common cement from surface to 103 feet, with a 4-foot marker of 2" pipe at the surface. Heavy mud was left in the hole below.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Henry R. Rimsaye
 Address P.O. Box 3194
Albuquerque, N.M.
 By M. K. W. G. G.
 Title Owner