


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



Land Office San Antonio, Tex., U.S.G.

Lease No. 82-540742

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January

, 1960


Well No. 22-122 is located 2400' ft. from [N] line and 600' ft. from [E] line of sec. 34
12/4, 22/2 17-18-22 W. 12-22
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
22-122 17-18-22 W. 12-22
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6710' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Rotary drilled to 1100' deep. 1100' to 1150' section was water zone, up to 1100' at approx. 1100', see for telephone instructions.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company 121 Valley Drive, Santa Fe, N.M.
Address _____

By Jorge S. Sandoval
Title Operator