

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Fort Fe, NM

Lease No. W. 04.0745

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

9 Feb, 19 62

Well No. 4-1 is located 300 ft. from N line and 300 ft. from E line of sec. 14


Range, Sec. and Sec. No. (Twp.) (Range) (Meridian)
Wildcat (Field) McKinley (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6715 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

hole plugged with 50' cement plug, site filled up, and site cleaned up, as per your written instructions.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George Semakovich

Address 101 Valley Drive

Fort Fe, New Mexico

By GEORGE S.

Title operator