


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe, New Mexico

Lease No. N.M. D48742

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

5 October, 1962

Well No. 14-3 is located 1960' ft. from N line and 1960' ft. from W line of sec. 14


SE 1/4, NW 1/4 (1/4 Sec. and Sec. No.) 17N, 4 W (Twp.) (Range) N.M.P.M. (Meridian)
wildcat (Field) Mckinley (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6691' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

Placed a 50' cement plug (with tubing in hole), and cleaned up site,



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George Sountatch

Address 121 Valley Drive,
Santa Fe, New Mexico

By Paulo CD

Title operator