


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Albuquerque, NM.
Lease No. NM. 041742
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	1
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	1
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	1
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	1
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	1
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	1
NOTICE OF INTENTION TO ABANDON WELL		1

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 7-D is located 15 ft. from N line and 340' ft. from E line of sec. 3
NE 1/4 Sec. 2 (1/4 Sec. and Sec. No.) T2N 11 W (Twp.) NADPM (Range) New Mexico (Meridian)
Albuquerque (Field) Albuquerque (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5353 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

*Have in 35' of 1 1/2" casing, and set it with 5-802
cement.
Remainder of hole lined by water pipe.*



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George S. Kauter, Inc.
Address 121 Valley Court, Albuquerque, NM.
By James W.
Title Operator