


4

Form 9-331a
(Feb. 1961)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-E358.4.
Form Approved.

Land Office Santa Fe, New Mexico

Lease No. N.M. 040742

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ABANDON	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

1 May, 1962

Well No. 7-D is located 3640' ft. from [N] line and 340' ft. from [E] line of sec. 2

NE 1/4, SE 1/4 of Sec. 2
(1/4 Sec. and Sec. No.)

17 N, 11 W
(Twp.) (Range)

N.M.P.M.
(Meridian)

Wildcat
(Field)

McKinley
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6765.3 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Will perforate 12 holes (per foot), 14 holes at 130' to 144', and 16 holes 193' to 202', using Logmasters Services, Inc.; fluid, Oklahoma to test oil potential zones as shown on resistivity-porosity-lateral electric log taken.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George Senatentch

Address 121 Valley Drive,
Santa Fe, New Mexico

By Same as -

Title operator -