



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office

Lease No.

Unit

RECEIVED

OCT 18 1962

U.S. GEOLOGICAL SURVEY
DIST. 1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

10 October, 1962

Well No. 7-D is located 364 ft. from N line and 140 ft. from E line of sec. 2

1/4 Sec. and Sec. No.

(Twp.)

(Range)

(Meridian)

(Field)

(County or Subdivision)

(State or Territory)

RECEIVED

OCT 17 1962

The elevation of the derrick floor above sea level is 67.5 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

we shot 2 inches per foot in the following potential oil zone: 130' to 144', 148' to 202', using 1/2 inch, 1/4 inch, 1/8 inch, after taking an electric log.

we drilled with 1 1/2 inch casing a trace of oil.

the well is now being drilled, before well is drilled, whether to abandon not.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George Construction

Address 211 Valley Drive, Fort Lupton, Pa.

By

Title