



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe, N.M.
Lease No. 131.040742
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

11 June, 1964

Well No. 7-D is located 2000' ft. from [N] line and 240' ft. from [E] line of sec. 2
NE/4, SE/4, sect. 2 17 North, 11 East 12N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Schriber N. Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 8705.3 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to 315' in 200 yards; tubing in well cemented top to bottom, and site cleared.

RECEIVED

JUL 22 1964

U. S. GEOLOGICAL SURVEY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company S. L. B. Co.

Address 121 Valley Drive, Santa Fe, N.M.

By George Denatovitch
(George Denatovitch)

Title operator