


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, NM,
Lease No. NM 140742
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

15 October, 1961

Well No. 7-A is located 3630' ft. from {N} line and 440' ft. from {E} line of sec. 2


NE/4 SE/4 (1/4 Sec. and 1/4 Sec. No.) 17 N 11 W (Twp.) NMPM. (Range) NMPM. (Meridian)
ident (Field) McKinley (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6697 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Abandonment: Considering that we were planning to go deeper (to Hesperia), probably after January 1962, we got phone permission while in front doing our initial drilling, to leave holes open until we returned to complete (a plug) and go a few feet deeper to cover the top of hole, in the meantime.
Cores: none taken (yet).



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Jorge Semetovich
Address 121 Valley Drive, Santa Fe, NM

By same as
Title operator