


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office W. V. L. B.

Lease No. 140744

Unit \_\_\_\_\_



SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

AUG 9 1963

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February, 1963

Well No. 23-1055 is located 334' ft. from [N] line and 500' ft. from [E] line of sec. 2

14 Sec. and Sec. No. 17 North 1 East 14 N. 20. E.  
(Twp.) (Range) (Meridian)  
14 (Field) 14 (County or Subdivision) W. V. L. B. (State or Territory)

The elevation of the derrick floor above sea level is 3700' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

our hole was 2', by rotary: plugged with cement plug & site cleared.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company 140744

Address 121 Valley Drive, Santa Fe, N.M.

By George L. Smith  
Title Inspector