


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio, Tex.
Lease No. _____
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 21-000 is located 2731' ft. from [N] line and 1544' ft. from [E] line of sec. 2
22/4, 23/4, 24/4 17 North, 11 West N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian) New Mexico
Alameda (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2731' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run by 2" casing (2' surface casing and test only) to 100' depth, with 2" casing in the remainder. From 100' depth to 150' with surface casing 2", in 150' site.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company 101 Valley View, San Antonio, Tex.
Address _____
By George Skutumpah
Title _____