



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 080677

Unit Star Lake

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	D. S. T.	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July-25, 19 63

Well No. 1 Star Lake is located 330 ft. from N line and 330 ft. from W line of sec. 5

NW-NW-NW-Sec-5 18N 5W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Mokinley New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6868.6.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

DST Entrada Fromation.
Interval Test 64 ft. 5175 to 5239
Recovered 4700 ft fresh water
Tool Opened 8:30 AM. Closed at 8:38 AM
Tool opened with fair blow for 7 minutes and died. Rotated for a 30 minutes, closed in pressure. Tool re-opened with fair blow which decreased to a very weak blow in 36 minutes and held the same throughout test. Took a 30 minutes final closed in pressure.

Halliburton Co.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company M. F. Abraham Star Lake Unit-1

Address 424-1st National Bank Bldg N.W.

Albuquerque, New Mexico

By Bear Abraham

Title _____

