



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 080677  
Unit Star Lake

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Surface Pipe Report</u>	<u>x</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July-9, 19 63

Well No 1 Star Lake located 330 ft. from [N] line and 330 ft. from [E] line of sec. 5  
NW-NW-NW Sec-5 18N 5W NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Mohinley New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 8883.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Set 365 ft of 19-3/8 in surface pipe with 185 sacks cement.  
BJ Cement Service.**

**ILLEGIBLE**

**RECEIVED**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company M. F. Abraham Star Lake Unit-1

Address 424-1st Nat Bank Bldg NW

Albuquerque, New Mexico

By M. F. Abraham

Title \_\_\_\_\_