

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 14-20-603-2676

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
JUL 30 1959
U.S. GEOLOGICAL SURVEY
FARMINGTON NEW MEXICO

July 30, 1959

Well No. 2 -I7 is located _____ ft. from [N] line and _____ ft. from [E] line of sec. I7
SE- NW 1/4 -I7 I9 N 5 W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated McKinley New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6618 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Intend to Plug and Abandon Well due to No Production. T.D. 4329'.
 Cased to 4320' w/9 I/2" J55 (4 I/2"). Perforated at 2375'. Re-Cemented
 w/200 sacks 10 % Gel. Left Plug at 2100'. Top Cement at 800'. Set Hole
 Marker at Top w/10 sacks.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Douglas Corporation - Caswell Silvers
 Address 327 Denver U S Nat'l.
Bank Bldg.
Denver, Colorado
 By Romer Allen
 Title Field Supt.

RECEIVED
JUL 31 1959
OIL CON. COM.
DIST. 3

