



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 87
Lease No. 079478
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Notice of intention to drill deeper x	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2-1-7 is located 330 ft. from N line and 330 ft. from E line of sec. 7
8 7 190 54 1-1-1
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Star Lake McKinley New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6637 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To drill deeper with air in order to test Gallup sand, to approximately 3400 feet. If productive 2 7/8" tubing will be cemented and perforated for testing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Goddie Mining Company

Address Suite 1500

Mile High Center

Denver, Colorado

By John K. Petty
John K. Petty
 Title Consulting Geologist
Harrington, New Mexico