For (F	Frm 9-881 a (Feb. 1951)							

TICE OF INTENTION TO DRILL TICE OF INTENTION TO CHANGE P TICE OF INTENTION TO TEST WAT TICE OF INTENTION TO RE-DRILL	LANSER SHUT-OFFOR REPAIR WELL	SUBSEQU SUBSEQU SUBSEQU	ENT REPORT OF SHOO ENT REPORT OF ALTE ENT REPORT OF RE-D	ER SHUT-OFF DTING OR ACIDIZING RING CASING RILLING OR REPAIR	
OTICE OF INTENTION TO SHOOT OF OTICE OF INTENTION TO PULL OR A OTICE OF INTENTION TO ABANDON	ALTER CASING	SUBSEQU	ENT REPORT OF ABAI ENTARY WELL HISTO	RY	
·	TE ABOVE BY CHECK MA		L trugual	<u> </u>	
ll No. 2-1-7 is loca	ted	(S)	_	(°44)	
INo. 2 is loca	1991		(Meridian)	Me	

his well was spudded on 8-11-60. Set 96 feet of 8-5/8" casing. comenting, and circulated same with 100 sacks. Brilling resumed in twelve hours 8-12-60. This easing was tested for thirty minutes with 1000# pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Gaddis Mining Company Address Sulte 1500 Mile Figh Center Conver, Colorado