

## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company <b>Chaco Oil</b>		Address <b>Box 8294, Albuquerque, N. M.</b>				
Lease <b>Santa Fe Pac R R</b>	Well No. <b>I-6</b>	Unit Letter <b>B A</b>	Section <b>29</b>	Township <b>20 N</b>	Range <b>9 W</b>	
Date Work Performed <b>5-29-61</b>	Pool <b>Red Mountain</b>			County <b>McKinley</b>		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations   
 ☐ Casing Test and Cement Job   
 ☒ Other (Explain):  
☐ Plugging   
 ☐ Remedial Work   
 **Corrected location**

Detailed account of work done, nature and quantity of materials used, and results obtained.

Corrected location of this water injection well, as shown on C-101 and C-128, is 395 feet from the north line and 1265 feet from the east line of Section 29, T20N, R9W, McKinley Co., N. M.



Witnessed by <b>Henry S. Birdseye</b>	Position <b>Co-owner</b>	Company <b>Chaco Oil</b>
--	-----------------------------	-----------------------------

## FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

## ORIGINAL WELL DATA

D F Elev. <b>6453 Gr</b>	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

## RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <b>Original Signed Emery C. Arnold</b>	Name <i>Emery C. Arnold</i>
Title <b>Supervisor Dist. # 3</b>	Position <b>Co-owner</b>
Date <b>JUN 2 1961</b>	Company <b>Chaco Oil</b>

The image is a severely degraded scan of a document page. It is characterized by extreme contrast, with large areas of black and significant white noise. Faint, illegible text is visible in the upper left and center. A vertical line of white noise runs down the right side. A small, dark, rectangular mark is visible near the bottom center.