

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY SINCLAIR OIL & GAS COMPANY - 601 Denver Club Building, Denver 2, Colorado
(Address)

LEASE Santa Fe 186 Raton Springs WELL NO. 1 UNIT 4PM S 23 T 20N R 7W

DATE WORK PERFORMED February 12, 1957 POOL Wilcoat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Spotted 16 sacks cement plug 3290 to 3240 ft.
Spotted 16 sacks cement plug 750 to 700 ft.
Capped hole with 5 sacks cement and installed 4" x 4' regulation pipe marker.
Plugged and abandoned 2-12-57

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____ (Company)	

OIL CONSERVATION COMMISSION

Name Emery O. Carter
Title General Manager
Date 2-18-57

I hereby certify that the information given above is true and complete to the best of my knowledge.
Name G. L. Weger
Position Asst. Div. Supt. - Production Dept.
Company Sinclair Oil & Gas Company