

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)


Name of Company <b>Chaco Oil Co.</b>				Address <b>P C Box 8294, Albuquerque, N. M.</b>			
Lease <b>Santa Fe Pacific R R</b>		Well No. <b>I-16</b>	Unit Letter <b>N</b>	Section <b>20</b>	Township <b>20 N</b>	Range <b>9 W</b>	
Date Work Performed <b>5-29-62</b>		Pool <b>Red Mountain</b>			County <b>McKinley</b>		

THIS IS A REPORT OF: (Check appropriate block)

- ☒ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):  
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Water injection well, Red Mountain water flood.  
 Spudded 5-1-62, drilling completed 5-2-62. T.D. 500'.  
 2" line pipe cemented at 480' w/10 sacks common cement.  
 5-29-62: tested casing @ 800 p.s.i. for 15 minutes: OK. Broke down formation with 110  
 gal. WCA. Broke down @ 950#.



Witnessed by <b>Henry S. Birdseye</b>	Position <b>Co-owner</b>	Company <b>Chaco Oil</b>
--	-----------------------------	-----------------------------

### FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

#### ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

#### RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by	Name <b>MB Birdseye</b>
Title	Position <b>co-owner</b>
Date	Company <b>Chaco Oil Co.</b>