

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. *****
7. Unit Agreement Name *****
8. Farm or Lease Name Santa Fe "A"
9. Well No. 1
10. Field and Pool, or Wildcat Hoopah Gallup
12. County McKinley

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator Shelly Oil Company
3. Address of Operator P.O. Box 730 - Hobbs, New Mexico
4. Location of Well UNIT LETTER "K" , 2070 FEET FROM THE South LINE AND 2050 FEET FROM THE East LINE, SECTION 1 TOWNSHIP 17-N RANGE 8-W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 6725' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Well plugged and abandoned in following manner:**
1. Spotted 35-cask cement plug from 1854-1700' (Hoopah).
 2. Spotted 35-cask cement plug from 700-550' (Point Lookout).
 3. Spotted 10-cask cement cap in top of 7-5/8" CD casing and installed 4" steel dry hole marker.
 4. All intervals not cemented were filled with heavy mud laden fluid.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(ORIGINAL SIGNED) **H. E. Asb**

SIGNED _____ TITLE **District Superintendent** DATE **July 11, 1966**

APPROVED BY *A. R. Kendrick* PETROLEUM ENGINEER DIST. NO. **3** DATE **7-27-66**
CONDITIONS OF APPROVAL, IF ANY: