

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN THIS MANNER  
(Other instructions on re-  
verse side)

Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.  
NM-8270

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Hospah9. WELL NO.  
44

10. FIELD AND POOL, OR WILDCAT

Lone Pine Dakota

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 12, T-17-N, R-9-W

12. COUNTY OR PARISH  
McKinley13. STATE  
New Mexico

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR  
Tenneco Oil Company

3. ADDRESS OF OPERATOR  
Suite 1200 Lincoln Tower Building, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
4950' F/WL and 660' F/SL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7074 GR

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well spudded 4-8-71 with 12-1/4" hole, drilled to TD of 65', Ran 2 jts of 8-5/8" 24# casing Landed at 65', cemented with 40 sacks, circulated. Tested casing and BOP to 1000 psi, held O.K. Drilled out with 7-7/8" hole to TD of 2850', Logged, Ran 87 jts of 5-1/2" 15.5# casing Landed at 2850', cemented with 350 sacks. Released Rig 4-11-71 and now waiting on completion unit.

RECEIVED

APR 16 1971

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Sr. Production Clerk

DATE

4-13-71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

