

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Fernandez Co.	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat	
12. County McKinley	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A
2. Name of Operator Northern Minerals, Inc.
3. Address of Operator 143 Rio Vista Place, Santa Fe, New Mexico 87501
4. Location of Well UNIT LETTER E , 1975 FEET FROM THE South LINE AND 685 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 14N RANGE 8W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 7381' G. L.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged and abandoned on January 10, 1972. Cement plugs were set at the following intervals:

1. 1947' - 2047' - across Dakota
2. 990' - 1090' - across Hospah Gallup
3. 235' - 285' - across Crevasse Canyon
4. 10 sacks in the surface.

A dry hole marker has been erected, the pits filled and the location restored.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Lloyd Davidson</u>	TITLE <u>President</u>	DATE <u>6-1-72</u>
APPROVED BY <u>Ernest C. Ames</u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>JAN 29 1972</u>
CONDITIONS OF APPROVAL, IF ANY:		