

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Northern Minerals, Inc.,		8. Farm or Lease Name Fernandez Co.
3. Address of Operator 143 Rio Vista Place, Santa Fe, New Mexico 87501		9. Well No. 4
4. Location of Well UNIT LETTER P , 840' FEET FROM THE South LINE AND 520' FEET FROM THE East LINE, SECTION 33 TOWNSHIP 15N RANGE 8W NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6940' G. L.		12. County McKinley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged and abandoned on March 17, 1972. Cement plugs were set at the following intervals:

1. 150' plug at 1950' to 2100'
2. 150' plug at 1080' to 1230'
3. 50' plug at 540' to 590'
4. 10' plug in surface

A dry hole marker has been erected, the pits filled and the location restored.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Lee J. Davidson</i></u>	TITLE <u>President</u>	DATE <u>6-1-72</u>
APPROVED BY <u><i>Gregory C. Linn</i></u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>10-29-72</u>
CONDITIONS OF APPROVAL, IF ANY:		