

## INSPECTION TICKET

DATE 8-9-73

INSTALLATION Chaco Mesa #1 LOCATION B-14-19N-7W  
OPERATOR Easton Petroleum Co. NEEDS SIGN \_\_\_\_\_  
POOL Wildcat FORMATION \_\_\_\_\_

LOCATION:

CLEAN \_\_\_\_\_ JUNKY \_\_\_\_\_ WEEDS \_\_\_\_\_  
OIL & WATER SPILL \_\_\_\_\_  
EDGES \_\_\_\_\_  
GENERAL APPEARANCE \_\_\_\_\_

PITS:

DIKE GOOD \_\_\_\_\_ NEEDS WORK \_\_\_\_\_  
FENCE GOOD \_\_\_\_\_ NEEDS WORK \_\_\_\_\_  
CONTAINS OIL \_\_\_\_\_ AMOUNT \_\_\_\_\_  
CONTAINS WATER \_\_\_\_\_ AMOUNT \_\_\_\_\_

PRODUCTION EQUIPMENT:

PUMP \_\_\_\_\_ BELT GUARD \_\_\_\_\_ FENCE \_\_\_\_\_  
SEPARATOR \_\_\_\_\_ DEHY \_\_\_\_\_ COMP \_\_\_\_\_  
CLEAN \_\_\_\_\_ DIRTY \_\_\_\_\_ WEEDS \_\_\_\_\_  
SAFE \_\_\_\_\_ FIRE HAZARD \_\_\_\_\_  
PIPED TO PIT \_\_\_\_\_ TANK \_\_\_\_\_  
LEAKS \_\_\_\_\_  
FLOWS TO PIT \_\_\_\_\_ GROUND \_\_\_\_\_  
CATHODIC PROTECTION UNIT \_\_\_\_\_

TANKS:

NUMBER \_\_\_\_\_ SIZES \_\_\_\_\_  
CLEAN \_\_\_\_\_ DIRTY \_\_\_\_\_  
OVERFLOW TO PIT \_\_\_\_\_  
LOAD LINE OK \_\_\_\_\_ PUDDLES OF OIL \_\_\_\_\_  
LEAKS \_\_\_\_\_ FIRE HAZARD \_\_\_\_\_  
FIRE WALLS \_\_\_\_\_ GOOD \_\_\_\_\_ NEED WORK \_\_\_\_\_  
FIRE WALL REQUIRED \_\_\_\_\_ RECOMMENDED \_\_\_\_\_

INSPECTED BY AR KendrickOWNER NOTIFIED BY MAIL, PHONE, DATE 9-6-73OFFICE FarmingtonOTHER REMARKS:Well P&A

Pit not filled  
Junk on and around location